




DEPARTMENT OF THE NAVY
COMMANDER MILITARY SEALIFT COMMAND
471 EAST C STREET
NORFOLK VA 23511-2419

4490
Ser N7/413
20 Apr 22

From: Commander, Military Sealift Command
To: Roy Strand, Chief Operating Officer, Goltens Worldwide Management Corp.
Subj: QUALIFICATION OF GOLTENS SERVICE CO., INC. AND GOLTENS HOUSTON, INC.
TO PROVIDE SERVICE AND REPAIR SUPPORT FOR MAN, WARTSILA, SULZER,
STORK WERKSPOOR, BERGEN AND MAK MARINE DIESEL ENGINES
Ref: (a) COMSC Instruction 4490.1C

1. Reference (a) establishes Military Sealift Command (MSC) policy and procedures for qualification requirements in the procurement of items critical to safety and the modification, repair and overhaul of those items assigned to Military Sealift Command vessels. The Instruction designates the MSC Engineering Director as the Design Control Activity (DCA) responsible to ensure that the design, production and performance standards are met for ship critical safety items. The instruction further assigns responsibility to the DCA to establish qualification requirements and to qualify and identify vendors that meet the criteria and standards for ship critical safety items.
2. Goltens Service Co., Inc. and Goltens Houston, Inc. are service departments of Goltens Worldwide Management Corp. Goltens Service Co, Inc. and Goltens Houston, Inc. requested consideration for qualification and submitted all required information. An MSC N7 Engineering DCA evaluation team reviewed that information and determined Goltens Service Co., Inc. and Goltens Houston, Inc. meet the relevant qualification criteria for maintenance and repair services on MAN, Wartsila, Sulzer, Stork Werkspoor, Bergen and MaK marine diesel engines.
3. Goltens Service Co., Inc. and Goltens Houston, Inc. are deemed qualified to provide OEM-equivalent maintenance and repair services on MSC ships for MAN, Wartsila, Sulzer, Stork Werkspoor, Bergen and MaK marine diesel engines. This qualification must be re-evaluated no later than 24 months from the date of this letter. Within its sole discretion, MSC may revoke qualification at any time if Goltens Service Co., Inc. and Goltens Houston, Inc. fail to provide quality maintenance and repair services, or if Goltens Service Co., Inc. and Goltens Houston, Inc. are unable to sustain the capabilities required in reference (a).
4. The MSC point of contact is Benjamin Hawbaker, ph: (757)341-6211; email: benjamin.f.hawbaker.civ@us.navy.mil


A. BUSK
By Direction